

## 5. Turn Signal Light and Hazard Light System

### A: WIRING DIAGRAM

#### 1. TURN SIGNAL LIGHT AND HAZARD LIGHT

<Ref. to WI-138, WIRING DIAGRAM, Turn Signal Light and Hazard Light System.>


### B: INSPECTION

#### 1. TURN SIGNAL SWITCH

<Ref. to LI-11, INSPECTION, Combination Switch (Light).>

#### 2. HAZARD SWITCH

Measure the resistance between hazard switch terminals.



Switch position	Terminal No.	Standard
OFF	2 and 3	1 MΩ or more
ON		Less than 1 Ω

#### 3. TURN SIGNAL AND HAZARD MODULE

Connect the battery and turn signal light bulb to the module. The module is properly functioning if it blinks when power is supplied to the circuit.

